

TegraStrip WBA50 Water Based Paint Remover

System	TegraStrip WBA50
Product Code:	WBA50
Product Description	TegraStrip WBA50 is an environmentally friendly paint stripping system. It is water-based, low VOC and non hazardous.
Key System Benefits	Due to its unique water-based formulation TegraStrip WBA50 has a mild odour and is safe to use for applicators and residents alike. Multi-layers of paint are steadily softened and lifted enabling easy and safe removal.
Main Uses	The TegraStrip WBA50 is typically used to remove multi-layered paints from communal area walls and ceilings. High rise, low rise, and sheltered housing have all been successfully stripped leaving clean plaster/masonry surfaces ready for fire-safe redecoration.
Pack Size	18 litres
Coverage Rate	1-4 m ² /litre per litre (due to the varied nature of paint stripping, coverage rates are approximate and a test patch should be carried out to establish accurate quantities.
Colour Range	Not applicable
Application	Brush or short/ pile roller. Do not allow to dry out or apply if condensation is likely to occur.
Mix Ratio	Single Pack
Pot life	Not applicable
Drying Time	Not applicable
Over Coating Interval	Not applicable
Flash Point	Not applicable
Storage	Store at temperatures between 5°C and 25°C.
Shelf life	6 months in original unopened containers
Health & Safety	Refer to current copy of Health and Safety Data Sheet
General Specification	

1. Degrease all surfaces to be stripped using TegraShield WDA800 Wash Down Agent. Abrade glossy surfaces.
2. To clean dry surfaces brush apply 1 full coat of TegraStrip WBA50 at a coverage rate of 1-4 m²/litre. Apply flame retardant plastic sheeting directly onto stripper forcing out any air bubbles. Ensure all joints and seams are adequately taped.
3. After 24 hours remove a piece of sheeting and test scrape a small area. If paint is sufficiently softened, scrape off using heavy duty steel scrapers. If paint is still firm near substrate replace plastic sheeting and allow more contact time for the stripper to penetrate before scraping paint off.
4. Very thick paint layers or highly absorbent surfaces may need steps 2 and 3 to be repeated until a satisfactory outcome is achieved.
5. To any remaining ingrained paint residues apply a thin coat of TegraStrip WBA50 and allow to dwell for 1 hour. Using heavy duty metal scouring pads thoroughly scour and remove all residue.
6. Wash down all stripped surfaces with clean water.

Disclaimer *The information given above is true and accurate to the best of our knowledge and is given in good faith but without any warranty. Please ensure you are reading a current and updated copy of this data sheet Integra Coatings Limited will not accept any claim for consequential or incidental damages.*

